Chapter 4 AC Machinery Fundamentals -> directly convert AC electrical energy/power into mechanical energy power Two Main Typess 1) Synchronous Machines - Most big generators -* magnetic field supplied by separate de source 2) Induction Machines - mainstay of electrical * magnetic field generated by applied ac source through transformer action Imagnetic induction 4.1 Simple Loop in a Uniform Magnetic Field 5 stator jo Joop Jas Top view of rotor er

4.1 cont. Voltage Induced in a Simple Kotating Loop Use Cind = (VXB). I to find induced voltage on all 4 sides of rotor Vab X B = Vab B Sind Qinto pase 1) Side ab I in direction of mire $e_{ab} = V_{ab} Blsin\theta = V Blsin\theta$ $\overline{V_{axis-b}} = -\overline{V_{axis-c}}$ Side be $\overline{V_{axis-b}} = -\overline{V_{axis-c}}$ axis Z) Side bc ebc = ecb = 0 Cancelout 3) Side col Ved × B = Ved Bsind ant of pase edc = Ved BASinB ede = J Blsind -> ditto Z) eda = Ead = 0 4) Side da

4.1 cont.

CTOT = Cab + Cbc + Cdc + Cda CTOT = ZV-Blsing where v=rwn & 0=wt NoteZrl = Area

ETOT = Zrwm Bl sinwmt of log eToT = ABW_ sin(wmt)

Max flux three loop when O=wnt= 900

Priax = A B

50 CTOT = Omax wom Sin (wint)



GENERATOR

3) Machine geometry size, materials, ...

3

41 cont. Torque Induced in a Current-Carrying Loop Nou assume loop carries a current i Each segment experiences a force $\overline{F} = i(\overline{I} \times \overline{B})$ current length magnitude vector in direction 11ti of current Sides ab + cd into pase ab into pase Vto risht $\overline{F}_{ab} = i(\overline{I} \times \overline{B})$ _→ ₹ July 1 Fed axis F =ilb (down) Out out $T_{ab} = \overline{r} \times \overline{F}_{ab}$ = rills sin BAR (cw) out to right $\overline{F}_{a}=i(\overline{I}\times\overline{B})$ -ilb (mp) \Rightarrow Note: $\Theta_{AB} = \Theta_{CO} = \Theta$ $T_{cd} = \overline{r} \times \overline{F}_{c1}$ =rilBsin Oco (cw) H.S. Seometry 1 HIPE Ends beidu ~ No torque, force parallel to axis of rotation. V 111 JF

4.1 cont. Total Torque is then 2rl = A = Area Trot = Tonduced = 2rilbsing 0=wnt = i BA sind = i BA Sin(wit) Note: Torque will vary sinusoidally (hard on machines) Alternately (take-off Wariation on magnetic dipole moments) => Tind = K Bloop Bs sing Tind = K Bloog X Bs A stator mas. flux density flux density produced by loop Blog = Mi 6 to loop geometry factor $K = \frac{AG}{M}$ Factorsi 1) Stato- Hux density !

1) Stator that density i 2) loop flux density which is proportional to i! 3) & between loop + stator flux 4) Machine geometry + materials (m)

4.2 Rotating Magnetic Field

-> Problem ul simple loop => to-que varies as loop rotating i Usolution -> W/ three windings carrying 3\$ power it is possible to produce. a rotating magnetic field w/ constant magnitude => constant torque! Bib' I Note that Bib' Ab Baar, Bbb', + Bec-Baar, Bbb', + Bec-Baar, Bbb', + Bec-Wrt one Wrt one another Show example Ban' > physical surface normal Note:

 $\overline{B}_{bb'} \rightarrow 11 \qquad (0 \ \theta = 170^{\circ})$ $\overline{B}_{cc'} \rightarrow 11 \qquad (0 \ \theta = 240^{\circ})$

Three-phase power & rotating magnetic field example

Cover one period $T(2\pi \text{ radians})$ n := 0..360 $\text{wt}_n := n \cdot \frac{2 \cdot \pi}{360}$

$$Baa_n := 1 \cdot sin(wt_n)$$

Compute magnetic fields for each phase.

Note: In addition to 120 deg or $\pi/3$ phase shift due to electrical signals, there is a 120 deg or $\pi/3$ physical rotation the the locations of the coils.

$$Btot_n := Baa_n + Bbb_n + Bcc_n$$

 $Bcc_n := 1 \cdot \sin\left(wt_n - \frac{2 \cdot \pi}{3}\right) \cdot e^{j \cdot \frac{2\pi}{3}}$

 $Bbb_n := 1 \cdot \sin\left(wt_n - \frac{\pi}{3}\right) \cdot e^{j \cdot \frac{\pi}{3}}$

Add up magnetic fields for each phase to get total magnetic field.



3_phase_rotating_mag_field.xmcd

What about the angle/phase of B_{tot}?

$$Btotang_n := arg(Btot_n) \cdot \frac{180}{\pi}$$



The linear variation of the angle/phase of the total magnetic flux density vector \mathbf{B}_{tot} over a total of 360 degrees in one period T (2π radians) tells us that the direction of \mathbf{B}_{tot} is rotating (with respect to time) at a rate of <u>one</u> rotation per period T of the three-phase power.

4.2 cont.

For this configuration, we got one rotation of Btor per electrical period.

BTOT = $f_e = f_m$ $\omega_e = \omega_m$

60Hz -> 3600 rpm = nm

2-poles

If we use multiple windings for each of the 3-phases, spaced evenly we Can increase the rotation frequency of Bror



-f=60Hz 7 1800rpm=nm

4.2 cont. In general, it we create & poles, we get 1/2 repetitions of the 3¢ windings and $\theta_e = \frac{f}{2} \theta_m$ $f_e = f_2 f_m$ We = 1/2 Wm $f_e = \frac{n_m^{rpm}}{120} \implies n_m = f_e \frac{120}{p}$ Reversing Direction of Magnetic Field Rotation why? Neverse Motor direction! a Swap any Zof 3 coils' currents i.e. trude bb' w/ cc'

MMF and Flux Distribution on Ac Machines (noter) Salient Notor Non-salient Rotar (easier to put windings (less air resistance) on rotor) > Common issues areair gaps + how Brot will not rotate Smoothly in actual. perfectly practice => Get coopsome ripple in B & Ø as rotor rotates => more slots / more windings > less ripple > practical limits

.

4.4 Induced Voltage in AC Machines レレ So far - 3\$ stator ac power produced rotating magnetic field Now, how does the magnetic field, produced by the rotor, induce a 30 voltage in the stator + ex fer single stator coil 18 stator ead r -- ed 1 Bm end to eba Urel = velocity of stator relative Vrel VR to rotor $B = B_m \cos(\omega t - \alpha) \text{ arbitrary choice (straight ap)}$ B = rotor may flux density I = length of wire segment, points Use $e = (\overline{\nabla} \times \overline{B}) \cdot \overline{I}$ in direction malkins Smallest & wrt FXB $e_{ba} = \nabla B J$ 1) Side ab = - V Bml cos (wt - 180°)

7) side bc $e_{cb} = 0$

4.4 cont.

3) side cd edc = V Bm l cos (wmt) 4) side da $e_{da} = 0$ $e_{ind} = -\nabla B_m lcos(ut - 180°) + \nabla B_m lcos(umt)$ -cos(wt) where V = Wmr = Zv Bm & cos(wmt) = Zrl Bm wm cos (wmt) max Ø end = Øwn cos(wnt) a sinsle turn could have For multiple turns (Nc) been sin() $e_{ind} = N_e \phi \omega_m \cos(\omega_m t)$ if a chosen differently STATOR

4.4 cont.

For 3 sets of coils 7 3\$ muchime $e_{aa'}(t) = N_c \phi \omega sin(\omega t) V$ $e_{bb'}(t) = N_c \phi \omega \sin(\omega t - 120^\circ) V$ $e_{cc'}(t) = \frac{N_c \phi_{cu} \sin(\omega t - 240^\circ)}{E_{max}} V$ $\omega_m = \omega_e = \omega = 2\pi f \left(T_{w, -p, l} - e^{-2\pi s_e} \right)$

Emax = No 4W $E_{RmS} = \frac{N_c \phi \omega}{N^2} = \frac{N_c \phi 2\pi f}{\sqrt{2}} = \sqrt{2} \pi N_c \phi f$ (per-phase (line-to-line depends on whether A or Y wirins)

4.5 Induced Torque in AC Machine -> due to interaction of rotar mag. field + stator mag, field Find = K Br × Bret Tind = K Br Bret Sinf Br = rotor may. flux density vector Bret = Br + Bs = net rotor + stater mag. flux density K = machine constant, depends on geometry and materials I = angle between Bret + Br (smallest) ΛBr Brot N By RHR ex. · Fri 0 Br curls toward Bret Motor 0 in Same direction Generator as Motor Tind = KBr Bret Sin S (CCW)

4.6 Winding Insulation in AC Machine

16

-> Bearings + winding insulation most common fuilure causes in AC Machines > Usually fails due to heat degradation of insulation (as opposed to dielectric breakdown) > ratings based on temperature class H cluss A, class B, ... 125°C 80°C →\$\$\$ See Fig. 4-20 G plot of life expectancy for each class of insulation vs. temperature.

17 4.7 AC Machine Power Flows & Losses

 $\eta = \frac{p_{out}}{p_{in}} \times 100\% = \frac{p_{in} - p_{ross}}{p_{in}} \times 100\%$

Motors Pin = electrical Pout = mechanical Generators lin = mechanical Pout = electrical

Losses (1) Copper loss (I²R) Similars totransformed 2) Core loss (V²/Reore) hysteresis teddy Currents 3) Mechanical losses (Friction, air resist.) 4) Stray loads (grab bag for losses above that can't be pinned down) Rule-of-thumb - 1% of full load

4.7 conti

Copper Losses -> Broken down further into those on stator (SCL) and those on rotor (RCL) AC (runs) In = current may, on phase A KA = resistance of wires on phase A $\beta_{SCL} = 3 I_A^2 R_A$ =) Assume all 30 identical en synchronous machine field winding on rotor (get to induction machines $P_{RCL} = I_F^2 R_F$ later) IF = current mas, of field winding (AC) RF = resistance of field winding

18

Core Losses -> hysteresis + eddy current ~ B² $\gamma (RPm)^{1.5}$

Mechanical Losses (Friction - bearings, brushes, slip rings, ... (moving parts in contact) (moving parts in contact) Windage - air resistance/drag on rotor & RPM³ Set values from No-load test on motor

19 4.7 cont. Power Flow Miagrams ilconv & Mechi power converted AC Generator (36) = Tind Wm > Pour = 3 Var In cost Pin = Topy Wm $= \sqrt{3} V_{\mu} I_{\mu} \cos \theta$ Stray Losses Mech. Core I2R losses Losses Losses I konv = Mind Wm Er Elect. power AC Motor (30) converted to mech > Pourt = Thad m Pin= 3V4.In Cost = 13 VILIE COSO Mach. Stray Core I²R Losses Losses Losses Losses

4.8 Voltage Regulation and Speed Regulation 20 VR > generators use this as a figure-of-merit -> how much does output voltage vary as load Increased from no-load to full-load $VR = \frac{V_{nL} - V_{FL}}{V_{FL}} \times 100\%$ SR - motors use this as a figure-of-merit 2 can motor maintain constant speed as load increased to full load? (RPM) $SR = \frac{n_{NI} - N_{FI}}{n_{FI}} \times 100\%$ $SR = \frac{\omega_{m} - \omega_{FL}}{\omega_{FL}} \times 100\%$ (rody)

Usually want VR + SR 20