

FIGURE 2-36 A three-phase transformer bank composed of independent transformers.




FIGURE 2-37 A three-phase transformer wound on a single three-legged core.




FIGURE 2-38 Three-phase transformer connections and wiring diagrams: (a) Y-Y




FIGURE 2–38 Three-phase transformer connections and wiring diagrams: (b) Y–Δ (*continued*)




FIGURE 2-38 Three-phase transformer connections and wiring diagrams: (c) Δ -Y (*continued*)




FIGURE 2-38 Three-phase transformer connections and wiring diagrams: (d) Δ - Δ (concluded)